

FITNESS CERTIFICATE

To be filled by the Inspection Officer (Assistant Engineer)
(Re:G.O.Ms,20/70/PWD Dt 23-01-1970)

- 1 Name of the officer - ARATHI SADHU
2 Name of School - ST:SEBASTIAN PUBLIC SCHOOL
3 Location with name of Education district - Udayamperoor
subdistrict - Ernakulam
- Tripunithura
- | | | |
|------|--------------|----|
| 5nos | 9.0x6.0x3.60 | GF |
| 5nos | 9.0x6.0x3.60 | FF |
| 5nos | 9.0x6.0x3.60 | SF |
- 4 Classification of building as per specified In col.4 of the application for fitness certificate and size - 2023-24
- 5 Period for which the certificate is issued - 2023-24
- 6 Nature of defect if any
- a)Foundation and basement - Nil
b)super structure - Nil
c) door and windows - Nil
d) wood work wrought and put up - Nil
e)roof - Nil
F) Flooring - Nil
g)Miscellaneous (cracks etc,) - Nil
- 7 Any major defects modified which willrender the building unsafe in any manner - Nil
- 8 Whether maintenance work have been done properly - Yes
whether the structure is sound or not for - *The Structure is sound under normal weather*
- 9 conduction classes - *condition*

Notes:1.The stability of the structure should be examined also with reference to location ,altitude,intensityof wind,exposure of flood etc .2.Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the institution was inspected by me on 30/05/23 and found to be fit /unfit to conduct classes, for the peroid 2023-24 for the reason stated above.

Udayamperoor
30-05-2023



Manager
St. Sebastian's Public School
Nadakkavu-P.O.
Udayamperoor - 682 307

Arathi
ARATHI SADHU
ASSISTANT ENGINEER
PEN - 681483
LID & EW SECTION
UDAYAMPEROOR GP
PH: 9885076020

[Signature]
Principal
St. Sebastian's Public School
Nadakkavu - P.O.
Udayamperoor-682307

FITNESS CERTIFICATE

To be filled by the Inspection Officer (Assistant Engineer)
(Re:G.O.Ms,20/70/PWD Dt 23-01-1970)

- 1 Name of the officer - ARATHI SADHU
- 2 Name of School - ST:SEBASTAIN PUBLIC SCHOOL
- 3 Location with name of Education district subdistrict - Udayamperoor
- Ernakulam
- Tripunithura
- 4 Classification of building as per specified in col.4 of the application for fitness certificate and size
- | | | |
|------|---------------|----|
| Inos | 6.0x6.0x3.70 | GF |
| Inos | 10.0x6.0x3.70 | GF |
| Inos | 6.0x1.80x3.70 | GF |
| Inos | 6.0x3.20x3.70 | SF |
| Inos | 6.0x6.0x3.70 | SF |
- 5 Period for which the certificate is issued - 2023-24
- 6 Nature of defect if any
- a) Foundation and basement - Nil
- b) super structure - Nil
- c) door and windows - Nil
- d) wood work wrought and put up - Nil
- e) roof - Nil
- f) Flooring - Nil
- g) Miscellaneous (cracks etc,) - Nil
- 7 Any major defects modified which will render the building unsafe in any manner - Nil
- 8 Whether maintenance work have been done properly - Yes
- whether the structure is sound or not for conduction classes - *The Structure is sound under normal weather condition*

Note: The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the institution was inspected by me on 30/05/23 and found to be fit /unfit to conduct classes, for the period 2023-24 for the reason stated above.

Udayamperoor
30-05-2023

Principal
St. Sebastian's Public School
Nadakkavu - P.O.
Udayamperoor-682307



Manager
St. Sebastian's Public School
Nadakkavu-P.O.
Udayamperoor - 682 307

ARATHI SADHU
ASSISTANT ENGINEER
BUILD & EW SECTION
UDAYAMPEROOR GP
PH: 9895876020

FITNESS CERTIFICATE

To be filled by the Inspection Officer (Assistant Engineer)
(Re:G O.Ms,20/70/PWD Dt 23-01-1970)

- 1 Name of the officer - ARATHI SADIHU
- 2 Name of School - ST:SEBASTAIN PUBLIC SCHOOL
- 3 Location with name of Education district subdistrict - Udayamperoor
Ernakulam
Tripunithura
- 4 Classification of building as per specified In col.4 of the application for fitness certificate and size
- | | | |
|------|----------------|----|
| 3nos | 6.82x6.10x3.70 | GF |
| 3nos | 6.82x6.10x3.70 | GF |
| 3nos | 6.82x6.10x3.70 | GF |
- 5 Period for which the certificate is issued - 2023-24
- 6 Nature of defect if any
- a)Foundation and basement - Nil
- b)super structure - Nil
- c) door and windows - Nil
- d) wood work wrought and put up - Nil
- e)roof - Nil
- f) Flooring - Nil
- g)Miscellaneous (cracks etc.) - Nil
- 7 Any major defects modified which willrender the building unsafe in any manner - Nil
- 8 Whether maintenance work have been done properly - Yes
- whether the structure is sound or not for conduction classes - *The Structure is sound under normal weather condition*
- 9 conduction classes

Note:1.The stability of the structure should be examined also with reference to location ,altitude,intensityof wind,exposure of flood etc .2.Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the institution was inspected by me on 30/05/23 and found to be fit /unfit to conduct classes, for the peroid 2023-24 for the reason stated above.

Udayamperoor
30-05-2023



Manager

St. Sebastian's Public School
Nadakkavu-P.O.
Udayamperoor - 682 307

ARATHI SADIHU
Assistant Engineer
PEN - 693483
U & EW SECTION
UDAYAMPEROOR GP
PK: 9895876020

Principal
St. Sebastian's Public School
Nadakkavu - P.O.
Udayamperoor-682307

FITNESS CERTIFICATE

To be filled by the Inspection Officer (Assistant Engineer)
(Re:G.O.Ms,20/70/PWD Dt 23-01-1970)


- 1 Name of the officer
- 2 Name of School
- 3 Location with name of Education district subdistrict
- 4 Classification of building as per specified In col.4 of the application for fitness certificate and size

- ARATHI SADHU
- ST:SEBASTAIN PUBLIC SCHOOL,
- Udayamperoor
- Ernakulam
- Tripunithura

Inos	5.7x12.0x3.70	GF
Inos	5.7x6.0x3.70	GF
Inos	5.7x6.0x3.70	GF
Inos	5.7x6.0x3.70	GF
Inos	5.7x5.78x3.70	GF
Inos	6.0x3.0x3.70	GF
Inos	6.0x6.0x3.70	GF
Inos	6.0x9.0x3.70	GF
Inos	6.0x9.4x3.70	GF
Inos	5.7x9.0x3.70	FF
Inos	5.7x9.0x3.70	FF
Inos	5.7x9.0x3.70	FF
Inos	5.7x6.0x3.70	FF
Inos	6.0x6.0x3.70	FF
Inos	6.0x5.78x3.70	FF
Inos	6.0x9.4x3.70	FF

- 5 Period for which the certificate is issued - 2023-24
- 6 Nature of defect if any
 - a) Foundation and basement - Nil
 - b) super structure - Nil
 - c) door and windows - Nil
 - d) wood work wrought and put up - Nil
 - e) roof - Nil
 - f) Flooring - Nil
 - g) Miscellaneous (cracks etc.) - Nil
- 7 Any major defects modified which will render the building unsafe in any manner - Nil
- 8 Whether maintenance work have been done properly - Yes
- 9 whether the structure is sound or not for conduction classes - *The Structure is sound under normal weather condition*

Note:1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate


Principal
St. Sebastian's Public School
Nadakkavu - P.O.
Udayamperoor-682307




Manager
St. Sebastian's Public School
Nadakkavu-P.O.
Udayamperoor - 682 307

CERTIFICATE

Certified that the institution was inspected by me on 30/05/23 and found to be fit /unfit to conduct classes, for the peroid 2023-24 for the reason stated above.

Udayamperoor
30-05-2023



Arathi
Assistant Engineer
ARATHI SADHU
ASSISTANT ENGINEER
PEN - 693483
LID & EW SECTION
UDAYAMPEROOR GP
PH: 9895876020

[Signature]
Principal
St. Sebastian's Public School
Nadakkavu - P.O.
Udayamperoor-682307



[Signature]
Manager
St. Sebastian's Public School
Nadakkavu-P.O.
Udayamperoor - 682 307